CBM
Occupational Health & Safety (OH&S) Framework



Scope of Brief

- Detail of Inspection
- Positive Observations
- Area of Improvement




Summary - Details of Inspection

Date/Time	Site/Project	Personnel Involved	No. of Positive Observations	No. of AFI
15/10/25	CAG-T3	Alfi	1	1
17/11/25	CAG-T3	Alfi	1	0
22/12/25	CAG-T3	Alfi	1	0

Your Facilities Management Partner

Positive Observations


1. Before commencing of works, tool-box meeting conducted by team lead & checking of equipment including of using the required PPE for the task in AHU T3 room. - 15/10/2025



Your Facilities Management Partner

Positive Observations

1. During auditing works, observed proper PPE & proper tools was use during removal of gauge pressure meter in T3 Chiller Plant room. - 17/11/2025






Your Facilities Management Partner

Positive Observations

1. During pre-survey works, using of platform ladder & adopting buddy system when doing work at height activity in T3 AHS room including housekeeping after works completed. - 22/12/2025







Your Facilities Management Partner


Area for Improvements

Project/Site	Observations	Areas for Improvement /Recommendation	Status
CAG-T3	Found extension plug with uninsulated cable sleeves	To use proper condition of cable extension plug	Removed from site
CAG-T3	Using of A-Frame ladder instead of platform ladder, Without proper buddy system	Replacing it with platform ladder for better stability & adopt buddy system on ladders	Immediate intervene & conduct briefing to workforce



CAG-T3
15/10/2025





Your Facilities Management Partner


CBM
CBM International
CBM Parking Solutions
CBM Security
Empire City Consultant
Systematic Laundry
ingenSys
www.cbm.com.sg
50 Years of Trust
Since 1971